

|                           |   |   |                         |
|---------------------------|---|---|-------------------------|
| <b>257.83<br/>(b) (2)</b> | <b>REPORT OF ANNUAL INSPECTION OF CCR SURFACE IMPOUNDMENT</b>   |   |                         |
|                           | <b>FACILITY NAME:</b> Plant Yates AP-A  |   |                         |
|                           | <b>OWNER/OPERATOR OF FACILITY:</b> Georgia Power Company  |   |                         |
|                           | <b>INSPECTION DATE:</b> January 17, 2017  |   |                         |
|                           | <b>INSPECTING ENGINEER:</b> Patrick B. Rhodes, P.E. (Georgia P.E. License # 24586)<br>Southern Company Services Fossil Dam Safety   |   |                         |
|                           | Based on the results of the inspection and review of the data provided by a qualified Professional Engineer, it is my professional opinion that the report has been completed in accordance with 40 CFR 257.83(b).  |   |                         |
| <b>(i)</b>                | <b>ANY CHANGES IN GEOMETRY OF THE IMPOUNDING STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION (YES OR NO)?</b>  | <b>N/A *</b>  |                         |
|                           | (IF YES, DESCRIBE): N/A   |   |                         |
| <b>(ii)</b>               | <b>LOCATION AND TYPE OF EXISTING INSTRUMENTATION</b>  | <b>N/A (no instrumentation)</b>   |                         |
| <b>(ii)</b>               | <b>MAXIMUM RECORDED READING OF EACH INSTRUMENT SINCE PREVIOUS ANNUAL INSPECTION</b>   | <b>N/A (no instrumentation)</b>   |                         |
| <b>(iii)</b>              | <b>APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF THE IMPOUNDED WATER SINCE PREVIOUS ANNUAL INSPECTION</b>   |   |                         |
|                           | MIN. DEPTH: N/A *   | MAX. DEPTH: N/A *   | PRESENT DEPTH: 0-ft**   |
|                           | MIN. ELEVATION: N/A *   | MAX. ELEVATION: N/A *   | PRESENT ELEVATION: N/A  |
| <b>(iii)</b>              | <b>APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF CCR SINCE PREVIOUS ANNUAL INSPECTION.</b>  |   |                         |
|                           | MIN. DEPTH: N/A *   | MAX. DEPTH: N/A *   | PRESENT DEPTH: 0-ft**   |
|                           | MIN. ELEVATION: N/A *   | MAX. ELEVATION: N/A *   | PRESENT ELEVATION: N/A  |
| <b>(iv)</b>               | <b>APPROXIMATE STORAGE CAPACITY OF IMPOUNDING STRUCTURE AT TIME OF INSPECTION.</b>  | N/A – AP-A is undergoing closure by removal and Plant Yates no longer burns coal, thus no longer generates CCR nor stores CCR in this area. |                         |
| <b>(v)</b>                | <b>APPROXIMATE VOLUME OF IMPOUNDED WATER AND CCR AT TIME OF INSPECTION</b>  | <b>WATER: 0 cu yds **</b>   | <b>CCR: 0 cu yds **</b> |
| <b>(vi)</b>               | <b>ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT AND APPURTENANT STRUCTURES (YES OR NO)?</b> | <b>NO</b>   |                         |
|                           | (IF YES, DESCRIBE): N/A   |   |                         |
| <b>(vii)</b>              | <b>ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION (YES OR NO)?</b>   | <b>N/A *</b>  |                         |
|                           | (IF YES, DESCRIBE): N/A   |   |                         |

\* This is the first 'annual inspection by a qualified professional engineer' performed in accordance with 40 CFR Part 257.83. This information will be included in subsequent annual inspection reports.

\*\* The ash pond is in the process of closure by removal and has been dewatered with only periodic stormwater present; all ash has been removed.

